

**Nevada Division of Environmental Protection
Red Tag Protocol Form**

Facility ID No. 8-000523

Facility Name: Rebel Store #2008

Address: 3235 N. Las Vegas Blvd., Las Vegas NV 89115

Contact Present On Site? ☒ **Yes** ☐ **No**

If yes then fill out the following:

Contact Name: Teressa Nilles

Contact Phone Number: (702) 644-1001

Date: 12/27/2022

Time of Event: 9:32 am

Inspector: Myles Holland

Witness: N/A

Purpose of Visit?

☒ **Application**

☐ **Reapplication**

☐ **Removal**

The following table identifies the most current tank and red tag tracking information:

Tank No.	Capacity	Product	Tank Location	Red Tag No.	Blue Seal No. 1	Blue Seal No. 2	Product Level
4	10,000-gallon	Diesel	West	109	162997	-	342
5	12,000-gallon	Diesel	East	456	-	-	7085

Method Used to Determine Product Level? ATG print out (If ATG attach printout to Form)

Summary of Visit:

I arrived on-site and spoke with Teressa (the attendant there) and explained the reason for my visit and why they are getting red-tagged. I then went to apply the red tag to the east diesel tank. The west diesel tank already had a red tag on it from 2018. I left a copy of the red tag notice, NOV3, and NDEP contact information with Teressa before I left.

REBEL 08
3235 N LAS VEGAS BLD
89115 LV NV

DEC 27, 2023 10:52 AM

SYSTEM STATUS REPORT

ALL FUNCTIONS NORMAL

INVENTORY REPORT

T 4:DIESEL
VOLUME = 342 GALS
ULLAGE = 9810 GALS
90% ULLAGE= 8794 GALS
TC VOLUME = 341 GALS
HEIGHT = 6.97 INCHES
WATER VOL = 0 GALS
WATER = 0.00 INCHES
TEMP = 76.1 DEG F

T 5:DIESEL
VOLUME = 7085 GALS
ULLAGE = 3067 GALS
90% ULLAGE= 2051 GALS
TC VOLUME = 7074 GALS
HEIGHT = 62.95 INCHES
WATER VOL = 0 GALS
WATER = 0.00 INCHES
TEMP = 71.3 DEG F

* * * * * END * * * * *

2023/12/27 09:56